





rys. 1


	a	b	c	d
	promienie R		promienie R	
1.	38	32,5	28,5	25,5
2.	85	77,5	70,5	62,5
3.	58,5	53,5	47	42
4.	45	38,5	35	31
5.	51	45	40	36
6.	75	67	61,5	54
7.	75	67	61,5	54

	e	f	g	h	i
	w stopniach / kąt		w mm		
1.	10	10	38	5	17
2.	10	10	25	8,5	24
3.	10	10	35	5,5	25
4.	10	10	35	5,5	20
5.	10	10	30	6,8	22
6.	10	10	30	8,0	33
7.	10	10	30	8,0	34




rys. 2

a	b	c	d	h
40	160	121	17	20
39,2	122,5	85,5	12	15
30	121	82	12	15
26	101	63	10	19
21	85	59,5	10	10
22	75,7	50	8	10
30	70	52	9	12
22	71	53	12	10
-	81	60,5	10	15



rys. 3


a	b	c	d	h
40	67,5	95	24	14
25	89	116	32	14
63	116	146	37	16



rys. 4


Możemy wykonać wkładki sprężynowe o innych rozmiarach, niż przedstawione na rysunkach - zgodnie z zapytaniem i życzeniem.

Wystarczy przesłać rysunek, wymiary lub wzór.




rys. 5

Wkładki sprzęgłowe w kształcie klocków wykonujemy w wielu różnych rozmiarach.




rys. 6

a	b	c	d
73	27	47	37
73	27	50	-




rys. 9



a	b	c	d
45	86	12	22
38	70	10	18
24	45,5	6	11

rys. 7



rys. 8

rys. 10

